

---

**From:** Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]  
**Sent:** 6/20/2014 2:52:16 PM  
**To:** Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]  
**Subject:** FW: Ash Pond ABC inspection 06/20/14  
**Attachments:** 20140620143059799.pdf

fyi

**From:** Jeffrey R Marcell (Generation - 3)  
**Sent:** Friday, June 20, 2014 2:33 PM  
**To:** Michael J Winters (Generation - 34)  
**Cc:** John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3)  
**Subject:** RE: Ash Pond ABC inspection 06/20/14

Attached.

There was some "oozing" or "seeping" from the West end of the A Pond sandbags. Water was ponding behind the bags in the area in the middle and East. Hard to tell if the ponded water in the middle was "seeping" because of the rip-rap against the edge of the sandbags. No evidence of water at the bottom of the A pond eroded area now covered in rip-rap.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)